



MATERIALS TESTING, INC.

55 LAURA STREET • NEW HAVEN, CONNECTICUT 06512 • (203) 468-5216
42 BOSTON POST ROAD • WILLIMANTIC, CONNECTICUT 06226 • (860) 423-1972

NVLAP #0320
Specific Scope Accredited

DATE: 03-14-11

REPORT: S-1007

CLIENT: McClure Construction Co.
61 Miner Road
Waterford, CT 06385

PROJECT: Client's Information

SUBJECT: LA ABRASION TESTING (ASTM C-535)

Material: 1 1/4" Crushed Stone

Sample No.: L-2367


Received: 3/3/11

Source: McClure Sand and Gravel, Waterford, CT

Loss to Abrasion: 43.1%

CT-DOT Form 816

Specification:	M.02.07 Item 3	< 50%
	M.03.01 Item 1(a)	< 40%
	M.05.01 Item 2	< 50%



Per our client, the above coarse aggregate is used in the processed aggregate base and gravel materials.

Materials Testing, Inc., Inspector
Bryan Kearns

William J. Soucy
William J. Soucy

1cc: Client

wlb