



MATERIALS TESTING, INC.

55 LAURA STREET • NEW HAVEN, CONNECTICUT 06512 • (203) 468-5216
42 BOSTON POST ROAD • WILLIMANTIC, CONNECTICUT 06226 • (860) 423-1972

NVLAP #0320
Specific Scope Accredited

DATE: 03-07-11

REPORT: M-1004

CLIENT: McClure Construction Co.
61 Miner Road
Waterford, CT 06385


PROJECT: Client's Information

SUBJECT: WASHED SIEVE ANALYSIS (ASTM C-136, D1140)

Material: Concrete Sand

Source: Groton Reservoir

Sampled by: and delivered by client to MTI on 3/3/11



| Sieve Size | Percent Passing | ASTM C-33 |
|------------------|-----------------|-----------|
| 3/8" (9.5mm) | 100 | 100 |
| #4 (4.75mm) | 96 | 95-100 |
| #8 (2.36mm) | 81 | 80-100 |
| #16 (1.18mm) | 62 | 50-85 |
| #30 (600µm) | 37 | 25-60 |
| #50 (300µm) | 14 | 10-30 |
| #100 (150µm) | 4 | 2-10 |
| #200 (75µm) | 2.1 | 0-3 |
| Fineness Modulus | 3.0 | 2.3-3.1 |

This material as sampled and delivered meets the listed specification.

Materials Testing, Inc.
Richard C. Kearns


William J. Soucy

1cc: Client

wlb